



Wiring and Installation instructions for North American Signal  
Company part #s: **LEDO-X and LEDR-X**

1. Each unit includes the LED head, 10' connector cable, and rubber grommet
2. Insert rubber grommet insuring that the lip of the grommet is clear of the hole and the grommet fits correctly
3. Follow these instructions-
  - **Red wire connects to positive**
  - Black wire connects to ground
  - Touch white wire to black ground wire to change patterns

**\*\*\*\*\*DO NOT TOUCH RED WIRE TO WHITE WIRE\*\*\*\*\***

4. Insert the LED head starting with one edge then pushing the remainder of the head into the grommet

